

FTT OSU Spare Parts List

Part Number	Part Type	Part Name	Unit Price	Notes	Instrument
4943-3	Burner	Calibration burner	POA		OSU
5084-4	Burner	Specimen pilot burner	POA		OSU
5110	Heat flux meter	Gardon gauge for OSU	POA	With flange	OSU
4992	Heater	Globar (Silicone carbide heating bar element)	POA		OSU
4998	Heater	Globar clip fixing tool	POA	Tool for clips holding braid to Globar	OSU
FTT0153	Heater	OSU Globar heater replacement kit	POA	Globars, ceramic sleeves, braid, clamps, clips and high temperature cable. Note: requires clip tool part # 4998	OSU
5102-4	Igniter	Spark igniter electrode	POA		OSU
5012-4	Sample	Specimen holder backing spring	POA		OSU
5013-3	Sample	Specimen holder frame	POA		OSU
5014-4	Sample	Specimen holder retaining pin	POA		OSU
5015-4	Sample	Specimen holder backup frame	POA		OSU
5016-4	Sample	Specimen holder drip tray	POA		OSU
5131	Sample	Specimen holder assembly	POA	No drip tray	OSU
5011-4	Thermocouple	Stack thermocouple and plug (type K)	POA		OSU